

Manohar Ganireddy

Coating Inspector

📍 530011 Visakhapatnam, India ✉ manoharInt6007@gmail.com ☎ +96871301250
in <http://linkedin.com/in/manohar-ganireddy-229baa187> 🇮🇳 Indian 📞 +919949278821

Education

2015 – 2019 Visakhapatnam, India	Bachelor in Mechanical Engineering <i>Pydah College Of Engineering and Technology</i> I have graduated in mechanical engineering from pydah engineering college and awarded in 1st class in degree.I have awarded 3rd prize in my technical model expo conducted in our college.
2013 – 2015 Visakhapatnam, India	Intermediate <i>Sri Gayatri jr.College</i> I have my done my 10+2 with main subjects of Mathematics,Physics and Chemistry.
2012 – 2013 Visakhapatnam, India	Matriculation <i>Amar Concept School</i>

Professional Experience

01/2022 – present Sohar, Oman	Coating inspector <i>L&T Energy Hydrocarbon</i> <ul style="list-style-type: none">• Witnessing and documenting of Coating/painting activities through the preparation of daily inspection Reports, through raising RFIs, inspection and documentation.• Review method statement of the works to be involved, verify materials compatibility for the specific equipment, Quality control procedure and Inspection and Test Plan.• Conduct painting system qualifications and prepare painter qualification records.• Responsible for incoming coating / painting material inspection and has to ensure whether these materials suit to meets the requirements of project specifications• Pre-installation inspection of surface, In-process inspections, Post application inspection, Final inspection of completion.• Coordinating with site supervisor, construction manager regarding the progress of the work.• To ensure material used on site as per client specifications.• Check and confirm all blasting and painting equipment/instrument to be used are in good condition/calibrated prior to commencement of work.• Ensure all surface preparation and application is in accordance with the specified standard.• Monitoring the working condition of air compressor and spray equipment and monitoring Blotter test for oil/water or other contaminations.• Monitoring WFT and DFT requirements as per specifications.• Detect coating faults and monitoring Holiday test prior to the client inspection in order to repair Holidays/pinholes as per standards.
----------------------------------	--

2019 – 2022
Visakhapatnam, India

Coating Inspector

Hindustan petroleum corporation limited

- Performing activities as per client requirements.
- Coating inspection on Tanks and Pipe lines.
- Monitoring weather conditions and making a record of changes.
- Monitoring WFT and DFT requirements as per specifications.
- To ensure material used on site as per client specifications.
- Witnessing and documenting of Coating/painting activities through the preparation of daily inspection Reports, through raising RFIs, inspection and documentation.

Certificates

National Association of corrosion engineers

I have certified as a NACE LEVEL-2 coating inspector.
Cert no-N-81965
Exp-Jan 29,2024

NDT-LEVEL-2

I have certified as a NDT-LEVEL-2 in DPT,UT,RT and VT

Technical Training

06/2018 – 06/2018

Internship Training

Hindustan Shipyard Limited-Visakhapatnam

I have done my internship ship training in Hindustan shipyard in Visakhapatnam.i have gone through ship hull berths fabrication and submarine repair and tug boat fabrication and some knowledge of the coatings used in marine.

Skills

Communication

I can speak,read and write Telugu hindi and English



Leadership

I have been a leading a team in the maintenance painting job of structural beams and supports.I am excellence in guiding and making the decisions to complete the task as simple as possible and efficient.



Time management

I work with according to the time and make planning to make the job to be completed on time



Declaration

I here thereby i declare that all above mentioned information is true and correct as per my knowledge.

Manohar Ganireddy
Visakhapatnam